

Receiving Waters

The following table lists all receiving waters, impairments and number of outfalls discharging to each waterbody segment.

OR

The information can be found in the following document or at the following web address:

--

Waterbody segment that receives flow from the MS4	Number of outfalls into receiving water segment	Chloride	Chlorophyll-a	Dissolved Oxygen/DO Saturation	Nitrogen	Oil & Grease/PAH	Phosphorus	Solids/ TSS/ Turbidity	E. coli	Enterococcus	Other pollutant(s) causing impairments
HARTSHORN BROOK (NHRIV700060906-05)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED TRIB. TO THE SOUHEGAN RIVER (NHRIV700060906-45)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
HONEY POT POND (NHLAK700060906-01)		☐	☒	☐	☐	☐	☐	☐	☐	☐	pH, Mercury
STUMP POND (NHLAK700061001-03)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
SOUHEGAN RIVER (NHRIV700060906-18)	3	☐	☐	☒	☐	☐	☐	☐	☒	☐	pH, Mercury, Aluminum
BEAVER BROOK - WOOLFORD DAM (NHIMP700060906-10)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK (NHRIV700060905-24)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
BABOOSIC LAKE (NHLAK700060905-01-01)	2	☐	☐	☐	☐	☐	☐	☐	☐	☐	Cyanobacteria hepatotoxic microcystins, Mercury, pH
BABOOSIC LAKE - TOWN BEACH (NHLAK700060905-01-02)	1	☐	☐	☐	☐	☐	☐	☐	☒	☐	Excess Algal Growth, Cyanobacteria hepatotoxic microcystins, Mercury
BABOOSIC LAKE - YOUNG JUDAEA BEACH (NHLAK700060905-01-03)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Cyanobacteria hepatotoxic microcystins, Mercury

PAVILLON BROOK (NHRIV700060905-25)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury, pH
UNNAMED BROOK - BETWEEN LITTLE BABOOSIC LAKE AND WASHER COVE BABOOSIC LAKE (NHRIV700060905-09)	1	☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury, pH
BABOOSIC BROOK (NHRIV700060905-10)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
SOUHEGAN RIVER (NHRIV700060906-16)		☐	☐	☐	☐	☐	☒	☒	☐	☐	Mercury, Copper
SOUHEGAN RIVER (NHRIV700060906-14)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
BEAVER BROOK (NHRIV700060906-01)		☐	☐	☐	☐	☐	☐	☒	☐	☐	Mercury, pH, Aluminum
Waterbody segment that receives flow from the MS4	Number of outfalls into receiving water segment	Chloride	Chlorophyll-a	Dissolved Oxygen/DO Saturation	Nitrogen	Oil & Grease/PAH	Phosphorus	Solids/ TSS/ Turbidity	E. coli	Enterococcus	Other pollutant(s) causing impairments
BEAVER BROOK (NHRIV700060906-03)	3	☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
BEAVER BROOK (NHRIV700060906-02)	2	☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK - TO SOUHEGAN RIVER (NHRIV700060906-17)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK (NHRIV700060906-39)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK (NHRIV700060906-38)	2	☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK - TO SOUHEGAN RIVER (NHRIV700060906-06)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
UNNAMED BROOK (NHRIV700060906-37)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
WITCHES BROOK (NHRIV700061001-02)	1	☐	☐	☒	☐	☐	☐	☐	☒	☐	Mercury, pH
UNNAMED BROOK - FROM CARRIAGE PLACE POND TO STUMP POND (NHRIV700061001-04)		☐	☐	☐	☐	☐	☐	☐	☐	☐	Mercury
PENNICHUCK BROOK - WITCHES BROOK (NHRIV700061001-07)		☐	☐	☒	☐	☐	☐	☐	☒	☐	Mercury, pH